

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**AN203**  
**SSW**  
**1/4-1/2**  
**0.332 mi.**  
**1752 ft.**  
**TO ROADWAY**  
**STILLWELL AT SURF AVE**  
**BROOKLYN, NY**  
**Site 1 of 6 in cluster AN**

**NY Spills** **S110242879**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**6 ft.**

**SPILLS:**

Name: TO ROADWAY  
Address: STILLWELL AT SURF AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0912716 / 2010-03-08  
Facility ID: 0912716  
Facility Type: ER  
DER Facility ID: 374513  
Site ID: 425621  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: D4  
SWIS: 2401  
Spill Date: 2010-03-07  
Investigator: RMPIPER  
Referred To: Not reported  
Reported to Dept: 2010-03-07  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial Vehicle  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2010-03-07  
Spill Record Last Update: 2010-03-08  
Spiller Name: JENNIFER WOUTINEN  
Spiller Company: NYC TRANSIT  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: JENNIFER WOUTINEN  
DEC Memo: "Small spill to roadway. Cleaned. Closed."  
Remarks: "onto pavemnet; clean up complete"

**All Materials:**

Site ID: 425621  
Operable Unit ID: 1181337  
Operable Unit: 01  
Material ID: 2175412  
Material Code: 0021  
Material Name: transmission fluid  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 6.00  
Units: G  
Recovered: 6.00  
Oxygenate: Not reported